

Produktauswahltabelle, Funktionen und Normeinhaltung



	Alfa e60P	Alfa e60A	Beta e90P	Beta e90A	Beta e90X	Beta e90 PFA	Beta e90 SFA	Beta e90 XFA	Beta e90 PFA Airline	Beta e90 SFA Airline	Beta e90 XFA Airline
Seitennummer für Bestellinformationen	49	50	51	52	53	54	56	58	60	62	64
Schweißen	●	●	●	●	●	●	●	●	●	●	●
Schneiden	-	-	-	●	●	-	●	●	-	●	●
Schleifen	●	●	●	●	●	●	●	●	●	●	●
Abschlussarbeiten	●	●	●	●	●	●	●	●	●	●	●
Positionsschweißen	●	●	●	●	●	●	●	●	●	●	●
Schweiß-filterscheibentyp	P	A	P	A	A	P	A	A	P	A	A
Größe der Sichtscheibe (mm)	99 x 52	96 x 35	100 x 78	100 x 60	97 x 47	100 x 78	100 x 60	97 x 47	100 x 78	100 x 60	97 x 47
Schutzhelmfunktion	-	-	-	-	-	-	-	-	-	-	-
Heftschweißfunktion	●	●	●	●	●	●	●	●	●	●	●
Optionales Vergrößerungsglas	●	●	●	●	●	●	●	●	●	●	●
E-Hand	●	●	●	●	●	●	●	●	●	●	●
MIG/MAG	●	●	●	●	●	●	●	●	●	●	●
WIG	●	●	●	●	●	●	●	●	●	●	●
Plasma-Schweißen	●	●	●	●	●	●	●	●	●	●	●
Fugenhobeln	●	●	●	●	●	●	●	●	●	●	●
Gewicht der Schweißschutzmaske	470 g	490 g	475 g	505 g	525 g	650 g	680 g	700 g	650 g	680 g	700 g
EN 175	B	B	B	B	B	B	B	B	B	B	B
AS/NZS 1337.1, Gesichtsschutz	●	-	●	●	●	●	●	●	●	●	●
EN 166	●	●	●	●	●	●	●	●	●	●	●
EN 12941	-	-	-	-	-	TH2	TH2	TH2	-	-	-
EN 14594 Umluftunabhängige Atemschutzsysteme	-	-	-	-	-	-	-	-	2B	2B	2B
AS/NZS 1716;	-	-	-	-	-	P1	P1	P1	●	●	●
EN 379, ADF	-	●	-	●	●	●	●	●	●	●	●
EN 169, passive Schweißfilter	●	-	●	-	-	-	-	-	-	-	-
AS/NZS 1338.1, Schweißfilter	●	-	●	●	●	●	●	●	●	●	●
EN 397, AS/NZS 1801 Schutzhelme	-	-	-	-	-	-	-	-	-	-	-

P = Passiv

A = Automatisch verdunkelnd

X = Erweitert

S = Standard

FA = FreshAir